

MASTERBUILT®

Autolgnite 545 Wire Harness Replacement

MB20041124, MB20042724











CAUTION



- Make sure the grill has cooled completely before handling to avoid burns.
- Some components may have sharp edges. Use caution and wear protective gloves to avoid injury.
- Power OFF the grill and disconnect the power from the wall before handling.

Tool needed for access and replacement: Phillips head screwdriver.

		 <p>ZIP TIE</p>
<p>1 Unplug fan and ignitor from controller. Unplug temp probe from controller (yellow plug not pictured).</p>	<p>2 Unplug fan and ignitor at fan side.</p>	<p>3 Remove zip tie at fan side.</p>
 <p>HOLE</p>		
<p>4 Remove left side shelf. Save for reuse. When you remove the shelf, you have to feed the wire harness wires through the side shelf hole one at a time (white plug and then black plug).</p>	<p>5 Remove grommet from grill body. Remove grommet from wire harness.</p>	
		 <p>GROMMET</p>
<p>6 Plug NEW wire harness into OLD wire harness at side shelf side of grill.</p>	<p>7 Feed new wire harness through grill body by gently pulling the NEW wire harness through the grill while attached to the OLD wire harness</p>	<p>8 Add grommet back to grill body. Reinstall side shelf. Reinstall all wire connections at controller side and fan side.</p>