## MASTERBUILT


## Autolgnite 545 Lower Burn Chamber Replacement

## MB20041124, MB20042724

## CAUTION 2

- Make sure the grill has cooled completely before handling to avoid burns.
- · Some components may have sharp edges. Use caution and wear protective gloves to avoid injury.
- Power OFF the grill and disconnect the power from the wall before handling.

Tool needed for access and replacement: Phillips head screwdriver.



Unplug fan and ignitor at fan.

Remove 4 screws from fan and ignitor assembly. Save this part for reuse.

Remove all 6 screws from lower burn chamber.

