MASTERBUILT

AuotIngite 545 Controller Kit Replacement

MB20041124, MB20042724



CAUTION



- Make sure the grill has cooled completely before handling to avoid burns.
- Some components may have sharp edges. Use caution and wear protective gloves to avoid injury.
- · Power OFF the grill and disconnect the power from the wall before handling.

Tool needed for access and replacement: Phillips head screwdriver.

